

Republic of the Philippines
Department of Agriculture

AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100

Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792

Email: atl\_director@atl.da.gov.ph & atl\_director@yahoo.com

URL: http://www.atl.da.gov.ph; www.e-extension.gov.ph

## REQUEST FOR QUOTATION

DATE: 10/10/2023

PURCHASE REQUEST NO.: ADMIN FUND 2023-10-188

CANVASS NO. 43

0	. 1			
Gen	t	am	an	٠

Please quote your lowest price, taxes included, and subject to the ter	ms and conditions that you may encounter
purposely for article (s) and/or service(s) enumerated below, stating	g the shortest time of delivery and submit you
quotation duly signed by your representative not later than	in the return envelope attached here with.

Very truly yours:

ITEM NO.	QTY	UNIT	ITEM AND DESCRIPTION	UNIT PRICE	TOTAL
	1	unit	Repair of COA Airconditioning Unit		
			1.5 TR Wall Mounted Type ACU		
	1	unit	Repair of ISD Chief Airconditioning Unit		
			3.0 TR Ceiling Mounted Type ACU		
1	1	unit	Repair of ISD Airconditioning Unit		
			3.0 TR Floor Mounted Type ACU		
	1	unit	Repair of ISD Airconditioning Unit		
			2.0 TR Wall Mounted Type ACU		
	1	unit	Repair of Assistant Director's Office Airconditioning Unit		
			3.0 TR Ceiling Mounted Type ACU		
	1	unit	Repair of ISO Airconditioning Unit		
			3.0 TR Ceiling Mounted Type ACU		
	1	unit	Repair of Printing Airconditioning Unit		
			5.0 TR Floor Mounted Type ACU		
	1	unit	Repair of LED Airconditioning Unit		
			3.0 TR Floor Mounted Type ACU		
	1	unit	Repair of Training Room Airconditioning Unit		
			3.0 TR Floor Mounted Type ACU		
	4 1	unit	Repair of Serrano Airconditioning Unit		
			3.0 TR Ceiling Mounted Type ACU		
			(Attach T.O.R. for standard requirements)		
PURPOS	SE:	1			
For the	repair of vario	us aircon	at the different offices of ATI-CO.		
Pls. subi	mit the followi	ng eligib	ility documents:		
	yor's/Business		• 387300000000000000000000000000000000000		
Inco	ome Tax Retur	'n			
Not	arized Omnibu	ıs Sworn	Statement		
			nber/Red Membership		
	tificate of Sole				
Note: Pl	s. provide also	the follo	wing: contact information such as email address and mobile/landline nur	nbers: Tax Id	entification
	and Bank Det		o and more full manner of the first terms of the fi		

 $I\ hereby\ certify\ that\ I\ am\ in\ the\ position\ to\ furnish\ the\ above\ article(s),\ service(s)\ at\ the\ prices\ and\ in\ quantities\ as$ called for except as I have indicated. The articles are available in our stock for immediate delivery to the Agricultural Training Institute, Elliptical Road, Diliman, Quezon City

MODEL:	
DELIVERY PERIOD:	
WARRANTY PERIOD:	
PRICE VALIDITY:	Signature Over printed name of proprietor/Manager or Authorized Representative
CANVASSED BY:	
DATE:	



# Republic of the Philippines Department of Agriculture AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100 Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792 Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

### TERMS OF REFERENCE

**PROJECT** 

Repair for VARIOUS AIRCONDITIONING UNITS

Installed in the Agricultural Training Institute -

Central Office

APPROVED BUDGET FOR THE CONTRACT (ABC)

PhP 387,000.00

LOCATION OF PROJECT:

Agricultural Training Institute, ATI Compound, Elliptical

Road, Diliman, Quezon City

## I. INTRODUCTION:

The ATI-CO has a various Airconditioning Unit installed in the ATI compound. These Airconditioning Units provides a sustainable, economical, and convenient investment to the public. To maintain its operation, annual preventive maintenance is required. However, when said units were maintained for preventive maintenance, Top Premiere (with approved Purchase Order) recommended said repairs be made, hence this request was made.

## II. EQUIPMENT ENROLLED:

Airconditioning Units located in various offices in ATI-CO specifically stated in the purchase requests. (hereto attached)

## III. SCOPE OF WORK:

SERVICES PROVIDER shall perform Corrrective Services such as repair of Airconditioning Units to ensure the operation and increase production life of the Airconditioning Units installed in the various offices of Agricultural Training Institute-Central Office.

NO	SCOPE OF WORK	CHECKLIST/DUTIES
1	Repair of COA 1.5TR Wall Mounted (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of FCCU PCB Main Board assembly 1.2 Repair and reconditioning of PCB assembly 1.3 Supply and installation of diode 1.4 Supply and installation of ICS 2. Leak Test 2.1 Leak test and leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant



## Republic of the Philippines Department of Agriculture AGRICULTURAL TRAINING INSTIT

AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100

Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792

Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com

URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

		4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
2	Repair of Assistant Director 3.0TR Ceiling Mounted (A.C.U)	1. Indoor Unit Installation 1.1 Reinstallation of indoor unit 1.2 Realignment of indoor unit to prevent leakage 2. Leak Test 2.1 Leak test 2.2 Leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
3	Repair of LEAD 5.0T.R Floor Mounted (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of ACCU Fan motor 1.2 Supply and mechanical installation of ACCU bearing 1.3 Re-oiling and re-shafting of Fan Motor 1.4 Supply and installation of capacitor 2. Leak Test 2.1 Leak test and leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation



Republic of the Philippines
Department of Agriculture

AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100
Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792
Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com
URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

		5.1 Monitoring and Observation
4	Repair of ISO 3.0T.R Ceiling Mounted (A.C.U)	1. Indoor Unit Installation 1.1 Reinstallation of indoor unit 1.2 Realignment of indoor unit to prevent leakage 2. Leak Test 2.1 Leak test 2.2 Leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
5	Repair of Training Room (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of FCCU PCB Main Board assembly 1.2 Repair and reconditioning of PCB assembly 1.3 Supply and installation of diode 1.4 Supply and installation of ICS 2. Leak Test 2.1 Leak test and leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
6	Repair of Printing 3T.R. Floor Mounted (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of FCCU PCB Main Board assembly 1.2 Repair and reconditioning of PCB assembly 1.3 Supply and installation of diode



Republic of the Philippines
Department of Agriculture
AGRICULTURAL TRAINING INSTITUTE
ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100
Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792
Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com
URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

		1.4 Supply and installation of ICS  2. Leak Test  2.1 Leak test and leak brazing  3. Evacuation Process  3.1 Vacuuming and recharging of Nitrogen gas  3.2 Release all gas until the pressure gauge reads zero  4. Charging Refrigerants  4.1 Charge the system with the required refrigerant  4.2 Charge the system with refrigerant as per weight required  4.3 Monitor the pressure readings as required by the manufacturer  4.4 Set ammeter to x15 range to get accurate current reading  5. Monitoring and Observation  5.1 Monitoring and Observation
7	Repair of ISD Chief 3.0T.R. Ceiling Mounted (A.C.U)	1. Indoor Unit Installation 1.1 Reinstallation of indoor unit 1.2 Realignment of indoor unit to prevent leakage 2. Leak Test 2.1 Leak test 2.2 Leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
8	Repair of ISD 3.0T.R. Floor mounted (A.C.U)	1. Indoor Unit Installation 1.1 Reinstallation of indoor unit 1.2 Realignment of indoor unit to prevent leakage 2. Leak Test 2.1 Leak test 2.2 Leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant



## Republic of the Philippines Department of Agriculture AGRICULTURAL TRAINING INSTITUT

AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100

Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792

Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com

URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

	T	T
		4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
9	Repair of ISD 3.0T.R Wall mounted (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of FCCU PCB Main Board assembly 1.2 Repair and reconditioning of PCB assembly 1.3 Supply and installation of diode 1.4 Supply and installation of ICS 2. Leak Test 2.1 Leak test and leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer 4.4 Set ammeter to x15 range to get accurate current reading 5. Monitoring and Observation 5.1 Monitoring and Observation
10, 11, 12 & 13	Repair of Serrano 3.0T.R Ceiling mounted (A.C.U)	1.Trouble shooting 1.1 Repair/replacement of FCCU PCB Main Board assembly 1.2 Repair and reconditioning of PCB assembly 1.3 Supply and installation of diode 1.4 Supply and installation of ICS 2. Leak Test 2.1 Leak test and leak brazing 3. Evacuation Process 3.1 Vacuuming and recharging of Nitrogen gas 3.2 Release all gas until the pressure gauge reads zero 4. Charging Refrigerants 4.1 Charge the system with the required refrigerant 4.2 Charge the system with refrigerant as per weight required 4.3 Monitor the pressure readings as required by the manufacturer



## Republic of the Philippines Department of Agriculture AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100 Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792 Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

4.4 Set ammeter to x15 range to get accurate current
reading
5. Monitoring and Observation
5.1 Monitoring and Observation

## IV. METHODOLOGY

- 1. Toolbox meeting
- 2. Initial Checkup and Testing of VARIOUS AIRCONDITIONING UNITS and monitoring of parameter
- 3. Conduct Rehabilitation/Repair for VARIOUS AIRCONDITIONING UNITS and replacement of defective parts
- 4. Testing and Turnover of VARIOUS AIRCONDITIONING UNITS and monitoring of after service parameters

### V. COMPLIANCE TO STANDARDS

- 1. DTI Certification of accredited supplier for refrigerant system;
- 2. DENR Compliance in charging and discharging of refrigerant affecting the Ozone layer;
- ASHRAE Standards in recharging and process of leak detection
   29.3 Refrigerant Safety
   29.14 Process of Leak detection
  - 23.14 Hocess of Bear detection
- 4. National Electrical Code (NEC);5. Philippine Electrical Code (PEC);
- 6. National Electrical Safety Code (NEC)
- 7. R.A 6969 Proper disposal of hazardous waste (refrigerant waste material)



# Republic of the Philippines Department of Agriculture AGRICULTURAL TRAINING INSTITUTE

ATI Building, Elliptical Road, Diliman, Quezon City, Metro Manila 1100 Tel. Nos. (63-2) 8929-8541 to 49 & 8928-7397 Fax No. (63-2) 8920-9792 Email: ati\_director@ati.da.gov.ph & ati\_director@yahoo.com URL: http://www.ati.da.gov.ph; www.e-extension.gov.ph

### VI. WARRANTY

- Warranty is meant to express the integrity of the labor and material supplied under normal use
  of the equipment to be free from defects. Damage due to normal wear and tear is not covered by
  warranty.
- 2. Moreover, consequent damages due to operational cause or natural events beyond control of man are not warrantable.
- 3. The Supplier/Contractor will give 3 months warranty on labor performed.
- 4. Spare parts supplied by the Contractor shall carry a *6 months limited warranty* from the time of installation.
- 5. Warranty repairs do not extend any further life to the supplier's basic warranty terms and conditions for the equipment.
- 6. Warranty repair cost is limited only to the cost of supplied items to bring the equipment in operation prior to the warranty repair.

Prepared By:

ARLENE GEMINIANA S. NILO, CPA
OIC Head, General Services

Approved:

REMELYN D. RECOTER, MNSA, CESO III